
Smoke and Dye Testing Summary

High Level Sewershed

Run Summary —										
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length			
S1028-233	Smoke	8/12/2009	ADS/TM	S21MM_003MH	Dry	Yes	641.57			



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary ————————————————————————————————————									
Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Hountain	Total Length		
S1028-233	Smoke	8/12/2009	ADS/TM	S21MM_003MI	H Dry	Yes	641.57		
Isolated Pip	oes ———								
Pipe ID		Upstream MH	Downstrea	Len m MH (f	gth D ft)	liameter (In)			
S21MM_0)54G1	S21MM_054UN	S21MM_02	21MH 5-	4.4	8			
S21MM_0	003G1	S21MM_003MH	S21MM_00	01MH 93.8	8194	10			
S21MM_0)31G1	S21MM_031MH	S21MM_02	21MH 77.3	3799	8			
S21MM_001G1		S21MM_001MH	S21MM_0	19MH 198	3.962	10			
S21MM_0)21G1	S21MM_021MH	S21MM_00)3MH 11.4	4616	10			
S21MM_0)10G1	S21MM_010MH	S21MM_00)3MH 73.8	8247	10			
S21MM_0)12G1	S21MM_012MH	S21MM_0	10MH 131	.727	8			

Observations & Photos